

Support Bulletin-25-10041

Date-3.26.2025

Title: Sentinel 1.6.0 boot up issues on non VT 4 Displays

Product Line: FAS

Model: Sentinel Software

Level: Public

Author(s):Bo Downing

Revision Letter: [Click or tap here to enter text.](#)



Overview: Sentinel 1.6.0 has issues booting up correctly with non VT4 displays. Confirmed Vario Fendt and Deere 2630

Links to Supporting Info:

Solution: Update to 1.6.1 Software for the Sentinel Software to load on the non VT4 display correctly. Sentinel 1.6.0 will not load on the non-supported displays correctly. This is for both Sentinel 1000 and 2000.