



# 396-4001Y1 Manual High Pressure SureBatch Parts List Manual



**NOTE: Make Sure Pump is Primed Before Operation. DO NOT RUN PUMP DRY**



# Overall System Layout



15 Gallon Cone Bottom Tank  
PN: 727-05-INFD15-19  
Tank Stand  
PN:727-29-INFD15ST

Manual High Pressure  
SureBatch  
(See page 3)



Inlet Plumbing Hose Kit  
(See page 4)



Page 2



Discharge Hose Kit  
(See page 5)





# Manual High Pressure SureBatch Parts List



3/4" Strainer Assembly  
PN: 521-06-3704Y1

SS Braided Hose  
PN: 283-01-038-06FPT

1/2" AG200 Hose—2 feet  
PN: 280-050-AG200



400 PSI Pressure Gauge  
PN: 137-LFG400-BM


Check Valve  
PN: 136-01-C600SS

3/8" MPT x #6 JIC Swivel Fitting  
PN: 161-09-6MP-6FJX

115VAC Motor  
PN: 210-3413Y1

Procon Metal Clamp  
PN: 352-01-1113

Procon Pump—1.16 GPM  
PN: 290-12-103A070R3



110 Volt Power Chord

ON/OFF Switch



# Inlet Plumbing Kit Parts List





# Inlet Plumbing Kit Parts List

3/8" x 20' Hose (Male JIC)  
PN: 283-038-06MJIC

Plumb to SureBatch Discharge



1-3/4" Acme Tank  
Connection Kit  
PN: 545-01-100100  
**OR**  
2-1/4" Acme Tank  
Connection Kit  
PN: 545-01-100150

Connects to NH3 Tank