Support Bulletin-SB-24-10012 Date-4.15.2024 Title: Actuator Incorrectly Reporting "Product Valve 'X' Failed to Close" Product Line: Spray Tender Model: QuickDraw 3000 Level: Public Author(s): Andy Boyle Revision Letter:



Overview:

Symptom: QuickDraw alarm "Product Valve 'X' Failed to Close" is present when the valve is in fact closed. This is caused by the software incorrectly reading the valve position sensor resulting in an incorrect reading.

Affected Systems: QuickDraw 3000 Cabinets manufactured between November 1st 2023 and April 9th 2024 utilizing a 1" KZ Valve Assembly (PN 103-2101Y1) may display a "Product Valve 'X' Failed to Close" Alarm while running a batch. Affected cabinets will contain a Valve Assembly PN 103-2101Y1 and Actuator PN 104-3614Y1

If your Cabinet meets all three of the following criteria proceed to the "Solution" steps outlined in this bulletin.

- 1. Cabinet was manufactured between November 1st 2023 and April 9th 2024 (See Image 1)
- 2. The 1" Product Valve Assembly displays sticker PN 103-2101Y1 (See Image 2)
- 3. The Product valve "Command Position" displays 0 and the Product Valve "Actual Position" displays a value larger than 5 (usually a position reading of 30-50). This can be viewed by pressing the "Manual Controls" Button on the run screen (See Image 3 outlined in red) and viewing the affected Product Valve (See Example Image 4 outlined in red)

Solution:

- Please follow the steps below to resolve the issue.
- 1. Proceed to <u>QuickDraw Software Updates</u>
- 2. Download and install the latest QuickDraw 3000 Software Version. (Software Rev: V2.4.7 or greater and Display Rev: 3.4.7 or greater)
- 3. If the issue persists after updating to current software then follow steps outlined in Images 5-12 below to turn off "CAN Jog Mode Enabled" This will display a Red X when off and a Green Check when on.



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

S	ystem Settings	1
Hide History Full Alarm	Default lbs/Gal	Manual Product Valve Select 2 Inch Venturi-Default
Grower/Farm/Field Tree	Units English	Kill Pump During Pause
Shuttle Inventory Alarms	Pump Start Mode Momentary Start-Default	Carrier Valve Control Blending
Carrier Inventory Alarms	Pump Start Time	
Battery Voltage: 0.00 Volts	0.0 Sec	
Month/Day/Year		$\mathbf{\Sigma}$
: 00 : 00 AM / /		Remote Settings RUN MENU

Image 7



Image 8





Image 10



Image 11



Image 12